Condition report

Needle: PDFREPORT-7715

Prepared for Ash Pemberton
14 Bellwether Lane, Flat 3

1. Roof

The felt at the north corner has lifted. Tacks have pulled clean through the substrate and the overlap is no longer weathertight. Recommend stripping the north third and relaying on a fresh deck.

2. Walls

The east wall shows hairline cracking above both window heads, consistent with historic settlement rather than active movement. Monitor for twelve months.

3. Drainage

The rear gully is blocked with leaf litter. The soakaway could not be located and may have been built over.

4. Summary

No urgent structural concern. Roof covering is the priority item.

PAGEFIVE-3307