
0
Define use case (function, actors, ODD)
1
Build lagging-indicator register
2
Proximate cause (prevention test)
3
Causal decomposition (OR / AND gates)
4
Earliest observable signal
5
Observability and independence check
6
Metric threshold θ and SPI threshold T
7
Attach to GSN safety case
loop over the lagging-indicator register
next lagging indicator