孔徑公差表



尺寸	Е			F			G		Н					Js		J		K		М		N		Р	R	単位: μ m 尺寸	
範圍	E7	E8	E9	F6	F7	F8	G6		H5	Н6	H7	H8	н9	H10			J6	J7	K6	K7	M6		N6	N7	P7	R7	範圍
(mm) 3 ~ 6	+ 32	+38	+50	+18	+22	+28	+12	+16	+5	+8	+12	+18	+30	+48	±4	± 6	+ 5	+ 6	+ 2	+ 3	- 1	0	- 5	- 4	- 8	- 11	(mm) 3 ~ 6
6 ~ 10	+ 20	+20 +47 +25	+20	+22	+10	+10	+ 4	+ 4	+6	+9	+ 15	+22	+36	+ 58 0		± 7.5	- 3 + 5	- 6 + 8	- 6 + 2	- 9 + 5	- 9 - 3	-12 0	-13 - 7	-16 - 4	-20 - 9	- 23 - 13	6 ~ 10
10 ~ 14 14 ~ 18	+ 25 + 50 + 32	+59 +32	+25 +75 +32		+13 +34 +16	+13 +43 +16	+ 5 +17 + 6	+ 5 +24 + 6	+8 0	+ 11 0	+ 18 0	+27 0	+43 0	+70 0	± 5.5	± 9	- 4 + 6 - 5	- 7 +10 - 8	- 7 + 2 - 9	-10 + 5 -12	<u>–12</u> – 4 –15	_15 0 _18	_16 _ 9 _20	-19 - 5 -23	-24 -11 -29	- 28 - 16 - 34	10 ~ 14 14 ~ 18
18 ~ 24 24 ~ 30	+ 61 + 40	+73 +40	+92 +40	+33 +20	+41 +20	+53 +20	+20 + 7	+28	+9	+13	+21	+33	+52	+84	± 6.5	±10.5		+12	+ 2	+ 6 -15	- 4 -17	0 -21	-11 -24	- 7 -28	-14 -35	- 20 - 41	18 ~ 24 24 ~ 30
30 ~ 40 40 ~ 50	+ 75 + 50	+89 +50	+112 +50	+41	+50 +25	+64 +25	+25	+34 + 9	+11	+16 0	+25 0	+39	+62 0	+100	±8	±12.5	.10	+14 -11	+ 3	+ 7 -18	- 4 -20	0 -25	-12 -28	- 8 -33	-17 -42	-25	30 ~ 40 40 ~ 50
50 ~ 65	+ 90	+106	+134	+ 49	+ 60 + 30			+ 40	+ 13		+ 30	+ 46 0		+120 0	± 9.5	± 15	+13 – 6	+18 -12	+ 4 –15	+ 9 -21	- 5 -24	0	-14 -33	- 9	-21 -51	- 30 - 60	50 ~ 65
65 ~ 80	+ 60							+ 10	0																	- 32 - 62	65 ~ 80
80~100	+107			+ 58 + 36	+ 71 + 36				+ 15	+ 22	+ 35			+140 0	± 11	±17.5	+16 - 6	+22 -13	+ 4 -18	+10 -25	- 5 -28	0 -35	-16 -38	-10 -45	-24	- 38 - 73	80~100
100~120	+ 72							+ 12	0	0															-59	- 41 - 76	100~120
120~140														+160 0	±12.5	±20						0 -40	-20 -45		-28 -68	- 48 - 88	120~140
140~160			+185 + 85								+ 40 0	+ 63 0	+100 0				+ 18 - 7									- 50 - 90	140~160
160~180																										- 53 - 93	160~180
180~200					+ 96 + 50	+122 + 50	+ 44 + 15						+115 0			±23	+22	+ 30 - 16				0 -46	-22 -51			- 60 -106	180~200
200~225				+ 79 + 50				+ 61 + 15	+ 20 0																-33 -79	- 63 -109	200~225
225~250																										- 67 -113	225~250
250~280	+162	+191			+108				+ 23	+ 32	+ 52	+ 81	+130	+210	±16	±26	+ 25	+36 –16	+ 5	+ 16	- 9	0	- 25	-14	-33	- 74 -126	250~280
280~315		+110	+110	+ 56	+ 56	+ 56			0	0	0	0	0	0			- 7		-27	- 36	-41	-52	-57	-66	-88	- 78 -130	280~315
315~355	+182		+265 +125		+119 + 62							+ 89 0	+140	+230	±18	±28.5	+29 - 7	+39 -18	+ 7 -29	+ 17	-10	0	-26		-41	- 87 -144	315~355
355~400	+125	+125							0		0			0						- 40	-46	-57	-62	-73	-98	_ 93 -150	355~400
400~450	+198	+232	+290		+131								+155			±31.5	+33		+ 8	+ 18	-10	0	-27	-17	- 45	-103 -166	400~450
450~500	+135	+135	+135	+ 68	+ 68	+ 68	+ 20	+ 20	0	0	0	0	0	0			- 7	-20	-32	- 45	-50	-63	-67	-80	– 108	-109 -172	450~500