## MANDAL ENGINEERING STANDARD OPERATING PROCEDURE (SOP) Welding

| Control No. : | Rev. No: 00 | Effective   | Department : |
|---------------|-------------|-------------|--------------|
| SOP/ME-MM/    |             | Date: 2022- | Safty        |
|               |             | 11-11       |              |

| Step<br>No | Activity(WHAT)      | Associated<br>Requirements/<br>Hazards/Impacts   | Responsibility<br>(WHO)   | Process / tools / PPEs (HOW)  | Remarks /<br>Reference  |
|------------|---------------------|--|---------------------------|---|---|
| 1          | Preparation for Job | SAFETY: Accidental<br>Contact With Live<br>Part, Damaged body<br>part ,& Crushed the<br>finger | Mechanical Shift Incharge | 1. Arrange all PPE for the work.  Safety Shoes Safety Helmet Cut resistance hand gloves Safety goggles Arm guard & Leg guard Compared to the safety requirement for self and ensure adequate safety precautions while working. Take Work permit from area owner, Fill up the LOTO permit with proper Isolation of power, working at Height take a Heigh | Note:Do not start job without permit and without positive isolation |

| 1. Injury by moving machines 2. Electrocution 3. Burn injury take p conce form I 3. Determinating before 4. Ensuring cleane | re starting the job,<br>permit from the<br>erned department in | Note: Maintenance to be done only after positive isolation of power. |
|---|--|--|
|---|--|--|

| PREPARED BY          | CONTRACTOR APPROVED BY | APPROVED BY          |
|----------------------|------------------------|----------------------|
| Shailesh masane      | Shrikant Mandal        | Shrikant mandal      |
| Signature with Date: | Signature with Date:   | Signature with Date: |