



General:									
TUV India Control Number: 0101			010112014920/37 (8116167470)		Branch:			Vadodara	
Notification Number: Email dtd			d: 12-05-2021		s) of Inspection) of Inspection:		13/05/2021	
Project Name & Location: Vizag Refi Project			inery Modernization Insp		nspection Location:		Silverline power infrastructure, Por, Ramangamdi.		
TUVIPL Client Name: AIROIL FL LIMITED			AREGAS PRIVATE End User Name:				AIROIL FLAREGAS PRIVATE LIMITED		
DEC / PMC / EPC Name: EIL			DEC / PMC / EPC Assignmen Number: (If applicable)		signment	B015			
Vendor Name & Location: Pvt.L Vado					P.O. Number: (Client PO on Vendor)		04/006390/20200335, A, Dated 17/03/2021		
Sub Vendor Name & Location:				P.O. Number: (If applicable – Vendor PO on Sub Vendor)			-		
Stages Of Ins	pection:								
☐ Kick Off / P	re Inspection Me	eting	Material Identification			☐ Interim	Stages		
☐ Document Review			Final Inspection			Re-Inspection			
Item Descript	ion:				T				
P.O. Item No.	Item Code	Item Descript	ion		UOM	P.O. Quantity		Offered Quantity	Acceptable Quantity
1	NA	X 30mm H w Job#006390 galvanized c	Perforated 2.5T X 50 mile with cover Hot Dip Galv. O Along with hot dip lamps for bottom type of X 2.5 mm with SS304		MTRS	250		250 (100 Nos)	250 (100 Nos)
2	NA	X 75mm H v Job#006390 plate with SS hot dip galva type cable tr	Perforated 2.5T X 150 with cover Hot Dip Galvo Hot dip galvanized Co 6304 Hardware Along vanized clamps for botto ay 150 X 75 X 2.5 mm lware (220 Nos)	upler with om	MTRS	275		275 (110 Nos)	275 (110 Nos)
3	NA	X 100mm H Coupler plat Along with he bottom type	adder type 2T X 750 m Hot Dip Galv. Job#006 e with SS304 Hardwa ot dip galvanized clamp cable tray 750 X 100 V lware (124 Nos)	390 re os for	Nos	186		186 Mtr (62 Nos)	186 Mtr (62 Nos)
Reference Documents:									
Sr. No. Document Name Client Doc			cument Number	ment Number Vendor Document Number			Approval Status		
1)	PR/MR/ARM	Not App	oplicable. Not Applicable.			Not Applic		ot Applicable.	

Form No. : F / INSP / VR / 11 – R12; Revision Date: 14.03.2020

Disclaimer: This IVR shall not be considered as final acceptance of inspected item(s). The final acceptance will be given through Inspection Release Note.

The inspection by TUV India Pvt. Ltd., review of Test Certificates / Reports and issue of Inspection Visit Report does not relieve the Client / Supplier / Manufacturer / Stockiest from their responsibility towards the Client / End User to supply the genuine material / item(s) and document(s) in full compliance with applicable Order, Specification, Technical, Quality, Quantity, Warranty, Guarantee requirements. Supplier / Manufacturer / stockiest is wholly legally responsible for genuineness of the material / item(s) supplied and document(s) submitted. TÜV India's responsibility is only limited to correctness of inspection results including review of the documents, within its agreed scope against written requirements and neither TUV India nor any of its group companies, associates or employees are in any way/ legally responsible for genuineness of the material / item(s) and document(s). If the calibration certificate(s) for the measuring instrument(s) / equipment(s) used during inspection do not have traceability to NABL / Other certifying bodies, then the scope of review is limited





SPIPL/AFPL/2020-21, DT-Approved with comments by QAP/ITP/QCP 2) Not Applicable. 05.08.2020 client. Approved with comments by 3) Drawing(s) Not Applicable. SPIPL/AFPL/001. client. 4) SPIPL/AFPL/002. Approved by client. Drawing(s) Not Applicable. 5) Drawing(s) Not Applicable. SPIPL/AFPL/003. Approved by client. 6) Drawing(s) Not Applicable. SPIPL/AFPL/004. Approved by client. 7) Drawing(s) Not Applicable. SPIPL/AFPL/005. Approved by client. 8) Datasheet(s) Not Applicable. Not Applicable. Not Applicable. 9) Procedure(s) Not Applicable. Not Applicable. Not Applicable. As per EIL Specification :- 7-10) Others(Specify) Not Applicable. As per approved QAP. 51-0333, Rev.3

Inspection Activities Carried Out:

Stages Witnessed:

1)

ITP/QAP Sr. No.; B1, Visual inspection carried out for ladder and perforated type cable tray lot wise (08 to 10 Nos Sample from offered Qty) - found Excess Zinc in perforated and Ladder tray holes, Uneven Waviness (Bend) observed in Ladder Covers, which is need to be rectified.

Note: Visual points are applicable for 100% quantity and manufacturer need to be rectify all the parts for above mentioned in points.

Documents Reviewed:

1) Not Applicable.

Details of Equipment(s) / Instrument(s) used for measuring / testing During Inspection:(Refer Notes)							
Sr. Ed	Detail of Equipment(s)/	Range	ID	Validity till Date	Calibration Certificate Number	NABL / OTHER CERT. BODIES / NABL Traceability	NON-NABL
	Instrument(s)					Please tick or Write Yes (
1)	Not Applicable.					-	-

- 1) Other Certifying bodies are: NPL-India, CIPM (International Committee for Weights & Measures), ILAC & APLAC MRA Signatories.
 2) Visiting inspector to ensure continued suitability for intended use, periodic maintenance, proper identification and valid calibration records and traceability to known National / International standards of the main 3) Non NABL if the calibration certificate(s) for the measuring instrument(s) (equipment(s) used during inspection do not have traceability to NABL / Other certifying bodies, then the scope of review is limited of 4) In lieu of table above inspectors may collect master list from manufacturer / vendor/sub vendor with all above details clearly highlighting the details of instrument(s) / equipment(s) used during inspection.

Conclusion (Acceptable / Not Acceptable / Acceptance subject to):

Not Acceptable till area of concern points closer.

IRN can not be issued for all items.

Pending activities:

NIL For This visit.

Identification of inspected Item(s):

NONE

Areas of Concerns:

Following are the area of concern:

Form No.: F / INSP / VR / 11 - R12; Revision Date: 14.03.2020

- 1) Visual inspection carried out for offered Ladder and Perforated Trays Observed Excess Zinc in Trays holes which need to be rectified (Rectification in-progress).
- 2) In Ladder tray covers observed uneven waviness same were clamped with ladder tray and found uneven gap up to 15 to 20 MM (Photos patched for reference).

Disclaimer: This IVR shall not be considered as final acceptance of inspected item(s). The final acceptance will be given through Inspection Release Note

The inspection by TUV India Pvt. Ltd., review of Test Certificates / Reports and issue of Inspection Visit Report does not relieve the Client / Supplier / Manufacturer / Stockiest from their responsibility towards the Client /End User to supply the genuine material / item(s) and document(s) in full compliance with applicable Order, Specification, Technical, Quality, Quantity, Warranty, Guarantee requirements. Supplier / Manufacturer / stockiest is wholly legally responsible for genuineness of the material / item(s) supplied and document(s) submitted. TÜV India's responsibility is only limited to correctness of inspection results including review of the documents, within its agreed scope against written requirements and neither TUV India nor any of its group companies, associates or employees are in any way/ legally responsible for genuineness of the material / item(s) and document(s). If the calibration certificate(s) for the measuring instrument(s) / equipment(s) used during inspection do not have traceability to NABL / Other certifying bodies, then the scope of review is limited only to technical content in the calibration certificate.

Copyright: This document is the property of TUV India Pvt. Ltd. and should not be reproduced, except in full without the consent of TUV India Pvt. Ltd. TUV India Pvt. Ltd. (TÜV NORD GROUP): (REGD. & HEAD OFFICE), 801, Raheja Plaza - I, LBS Marg, Ghatkopar (West), Muml Tel: + 91 22 66477000, Email: inspection@tuv-nord.com; Website: www.tuv-nord.com/in.





3) Vendor has to submit report of QAP Clause No - C2 (Mass of Zinc coating by stripping test) for verification as per QAP. 4) Point No - 2 & 3 mentioned in IVR-010112014920-37-1-Rev.0, DT-29.04.2021 need confirmation from client as discussed.						
Above points discussed with client (Mr. Irfan).						
Non Conformities raised / Discrepancies observed during inspection (If Any, Mention TUV India NCR Number):						
NIL						
Attachments:						
Inspection records – Total Page Nos.	03	Master List of calibrated Instruments / equipment :				
Inspection Photos – Refer Page Nos.	4 to 6	□ Others (Specify) :				
Authorised Signature:						
TUV India representative:		Vendor / Sub Vendor Representative (If Applicable):				
TOV India Hardi	Reset .					
Name:Hardik Patel Date:13/05/2021		Name:				
Distribution List: ☐ TUVI Client / End User ☐ TUVI Executing Branch / TUV Originating Branch ☐ Vendor / Sub Vendor						
Revision Number (If Applicable): 0 – This Document Supersedes IVR No. :-						

Form No. : F / INSP / VR / 11 - R12; Revision Date: 14.03.2020

Disclaimer: This IVR shall not be considered as final acceptance of inspected item(s). The final acceptance will be given through Inspection Release Note.

The inspection by TUV India Pvt. Ltd., review of Test Certificates / Reports and issue of Inspection Visit Report does not relieve the Client / Supplier / Manufacturer / Stockiest from their responsibility towards the Client / End User to supply the genuine material / item(s) and document(s) in full compliance with applicable Order, Specification, Technical, Quality, Quantity, Warranty, Guarantee requirements. Supplier / Manufacturer / stockiest is wholly legally responsible for genuineness of the material / item(s) supplied and document(s) submitted. TÜV India's responsibility is only limited to correctness of inspection results including review of the documents, within its agreed scope against written requirements and neither TUV India nor any of its group companies, associates or employees are in any way/ legally responsible for genuineness of the material / item(s) and document(s). If the calibration certificate(s) for the measuring instrument(s) / equipment(s) used during inspection do not have traceability to NABL / Other certifying bodies, then the scope of review is limited

IVR-010112014920/37-2-Rev.0



Inspection Pictures

Offered Material for inspection.




Offered Material for inspection.



Offered Material for inspection.



Visual inspection carried out observed excess zinc in holes.



Visual inspection carried out observed excess zinc in holes.



Visual inspection carried out observed excess zinc in holes.



Disclaimer: This IVR shall not be considered as final acceptance of inspected item(s). The final acceptance will be given through Inspection Release Note.

The inspection by TUV India Pvt. Ltd., review of Test Certificates / Reports and issue of Inspection Visit Report does not relieve the Client / Supplier / Manufacturer / Stockiest from their responsibility towards the Client / End User to supply the genuine material / item(s) and document(s) in full compliance with applicable Order, Specification, Technical, Quality, Quantity, Warranty, Guarantee requirements. Supplier / Manufacturer / stockiest is wholly legally responsible for genuineness of the material / item(s) supplied and document(s) submitted. TÜV India's responsibility is only limited to correctness of inspection results including review of the documents, within its agreed scope against written requirements and neither TUV India nor any of its group companies, associates or employees are in any way/ legally responsible for genuineness of the material / item(s) and document(s). If the calibration certificate(s) for the measuring instrument(s) / equipment(s) used during inspection do not have traceability to NABL / Other certifying bodies, then the scope of review is limited only to technical content in the calibration certificate.

IVR-010112014920/37-2-Rev.0



Inspection Pictures

Visual inspection carried out observed uneven waviness in Ladder tray covers.

Visual inspection carried out observed uneven waviness in Ladder tray covers.





Clamping done in wavinesss cover with Ladder (Client Reference).

Clamping done in wavinesss cover with Ladder (Client Reference).





Clamping done in wavinesss cover with Ladder (Client Reference).

Rectification in progress for excess zinc.



Form No. : F / INSP / VR / 11 - R12; Revision Date: 14.03.2020



Disclaimer: This IVR shall not be considered as final acceptance of inspected item(s). The final acceptance will be given through Inspection Release Note.


The inspection by TUV India Pvt. Ltd., review of Test Certificates / Reports and issue of Inspection Visit Report does not relieve the Client / Supplier / Manufacturer / Stockiest from their responsibility towards the Client / End User to supply the genuine material / item(s) and document(s) in full compliance with applicable Order, Specification, Technical, Quality, Quantity, Warranty, Guarantee requirements. Supplier / Manufacturer / stockiest is wholly legally responsible for genuineness of the material / item(s) supplied and document(s) submitted. TÜV India's responsibility is only limited to correctness of inspection results including review of the documents, within its agreed scope against written requirements and neither TUV India nor any of its group companies, associates or employees are in any way/ legally responsible for genuineness of the material / item(s) and document(s). If the calibration certificate(s) for the measuring instrument(s) / equipment(s) used during inspection do not have traceability to NABL / Other certifying bodies, then the scope of review is limited only to technical content in the calibration certificate.

IVR-010112014920/37-2-Rev.0



Inspection Pictures

After rectification 5 Nos tray check found ok but vendor has to done visual in all the trays.



Form No. : F / INSP / VR / 11 - R12; Revision Date: 14.03.2020

Disclaimer: This IVR shall not be considered as final acceptance of inspected item(s). The final acceptance will be given through Inspection Release Note.

The inspection by TUV India Pvt. Ltd., review of Test Certificates / Reports and issue of Inspection Visit Report does not relieve the Client / Supplier / Manufacturer / Stockiest from their responsibility towards the Client / End User to supply the genuine material / item(s) and document(s) in full compliance with applicable Order, Specification, Technical, Quality, Quantity, Warranty, Guarantee requirements. Supplier / Manufacturer / stockiest is wholly legally responsible for genuineness of the material / item(s) supplied and document(s) submitted. TÜV India's responsibility is only limited to correctness of inspection results including review of the documents, within its agreed scope against written requirements and neither TUV India nor any of its group companies, associates or employees are in any way/ legally responsible for genuineness of the material / item(s) and document(s). If the calibration certificate(s) for the measuring instrument(s) / equipment(s) used during inspection do not have traceability to NABL / Other certifying bodies, then the scope of review is limited