DERNI PTY LTD A.C.N. 002 263 872 / A.B.N. 41 002 263 872 For Barkersupa Pty Ltd A.C.N. 604 006 117 / A.B.N. 98 715 100 390 trading as

Harvey Norman AV/IT Superstore Mt Barker

6 Dutton Road

Mt Barker SA 5251

Phone: 08 8393 0800 Fax: 08 8393 0899 ______ SUPPLIER'S COPY TAX INVOICE 17/10/16 16:44:50 147 CREDIT CLAIM 2219587 Contact : 60 HPhelan Supplier # : 510708 YAMAHA MUSIC AUSTRALIA PTY LTD PO BOX 268 SOUTH MELBOURNE Franchisee #: 14760 3205 Phone : 1300661977 Fax : 1800331119 Fran : 060 Invoice #: 2076396 Invoice Date: 07/12/15 Freight \$: 5.24 Dear Sir/ms, We claim a credit to our account in respect to the matter detailed below. PLEASE NOTE THAT YOU HAVE UNTIL 16/12/16 TO REJECT THIS CLAIM, OTHERWISE IT WILL BE CONSIDERED FINALISED IN OUR FAVOUR. Reason for our claim: CLAIM-RETURN FOR CR R.A. No: RA# Notes: FAULTY - RETURN FOR CREDIT Qty Price Product Code Description of Goods 1.00 349.35 YHT1810B YAMAHA 5.1 HTIB INV2076396 +9916291 X1 HNOPS12559 S/N T658215XZ Product faulty. Picture does not hold any longer than five minutes then goes to snow, then black. Had it professionally installed and also checked again by professional installation man, to no avail. ______ A.B.N. No : 41 002 263 872 G.S.T. \$: 34.94 TOTAL CLAIM \$: 384.29 Authorised by: HPHELAN Raised by: CHECKED PACKED Quantity Ву Quantity Ву Con Note No Drivers Signature Carrier Company Drivers Veh Date Name reg E&OE.

Barkersupa Pty Ltd A.C.N. 604 006 117 / A.B.N. 98 715 100 390 as trustee of the Barkersupa No 2 Trust trading as

Harvey Norman AV/IT Superstore Mt Barker

6 Dutton Road

Mt Barker SA 5251

Phone: 08 8393 0800 Fax: 08 8393 0899

TAX INVOICE

INVOICE REPRINT 10/10/2016 1816163

JAKOB ANDERSSON Assist HPhelan

Χ Cust # 0416444045

MOUNT BARKER, SA, 5251 SType CASH SALE

Oper HPhelan

Product	Qty	Price	Total
YHT1810B	1	499.00	499.00
YAMAHA 5.1 HTIB * TAKEN * on 10/1	0/16		
YHT1810B YAMAHA 5.1 HTIB	-1	499.00	499.00

* RETURNED * on 17/10/16

T658215XZ

Product faulty. Picture does not hold an y longer than five minutes then goes to snow, then black. Had it professionally installed and also checked again by professional installation man, to no avail.

Previously had the same product and same problem.

GST Content

0.00

Total:

0.00