

Service News# SJV30802

Date:30 August 2002

Relevant News: -----

Page: 1/2

Subject: Int. Video Output or Not Turning On

Model: DVD-S520/S5450

## **SUBJECT**

Change of resistor(R3256- 680Ohm) value in power supply to correct above fault

## **PURPOSE**

To ensure -5V startup

## This SERVICE is applied to when:

Apply when the above fault is observed

\_

