


SDLE-18

ASSEMBLY MANUAL

装配说明书


螺丝说明

Screw specification



M3*8, d=M3, L=8

M5*40, d=M5, L=40



Don't let the cart run off the rail!!

linear guide



rust preventive lubricating oil




spray rust preventive lubricating oil on linear guide.

STEP 1







M5*8

M5 T nut














STEP 2




























M4*25

M4 nut

M5*8

M5 nut






















STEP 3









M3*8










M4 T nut


































M5*8 M5 T nut














STEP 4













电机2


电机1










STEP 5




























M3 T nut


M5 gasket


M3*6












M3*8

M3*6+6



M3 nut

M3*6

