

300mm Precision Wafer Dicing Saw

Authoritative Model Technical Manual & Diagnostic Reference | VAI-MAN-WS-001

NOTICE: SYNTHETIC PROTOTYPE TECHNICAL MANUAL

This document is artificially generated for the VectorAI demonstration and software development.

The specifications, thresholds, service-life values, maintenance intervals, and operating parameters are synthetic and must not be used for real industrial equipment operation or maintenance.

1. Machine Overview & Manufacturing Context

Equipment Model:	300mm Precision Wafer Dicing Saw	Document ID:	VAI-MAN-WS-001
Machine Type Key:	wafer-saw	Cleanroom Bay / Stage:	Bay 1: Wafer Dicing & Prep
Document Version:	1.0	Release Date:	2026-08-27

Dual-spindle 300mm wafer dicing system utilizing high-speed diamond blades (up to 60,000 RPM) with DI water cooling jets to singulate silicon, GaN, and GaAs wafers into discrete micro-dies.

Process Flow: Wafers mounted on UV dicing tape are placed on a porous ceramic vacuum chuck table. High-pressure DI water jets cool the blade kerf and flush silicon swarf while dual microscope cameras align scribe lanes with sub-micron precision.

2. Major Subsystems & Critical Components

Subsystem / Component	Primary Function	Key Parameters	Degradation Indicators
Air-Bearing Spindle Assembly	Drives diamond blade at 30,000 to 60,000 RPM with sub-micron radial runout.	Spindle speed (RPM), radial vibration (mm/s), motor load (%).	High-frequency harmonic vibration (>1.2 mm/s), bearing temperature rise.
Resinoid Diamond Blade	Precision mechanical shearing along wafer scribe lines.	Blade outer diameter, kerf width (μm), blade wear index (μm).	Wafer backside chipping (>25μm), kerf widening, blade edge loading.
DI Water Coolant Delivery	Cools cutting interface and evacuates silicon particulate swarf.	Coolant temperature (°C), nozzle pressure (bar), resistivity (MΩ).	Nozzle pressure drop (<1.5 bar), coolant temperature drift (>28°C).
Porous Ceramic Vacuum Chuck	Immobilizes wafer dicing tape carrier during high-velocity cutting.	Holding vacuum (kPa), chuck table flatness (μm).	Vacuum leakage (>-60 kPa), particulate clogging in ceramic pores.

3. Sensor Telemetry & Threshold Matrix

Threshold boundaries configured for real-time telemetry monitoring and automatic anomaly triggers:

Sensor Name & ID	Unit	Normal Range	Warning Range	Critical Range	Direction
Spindle Radial Vibration vibration_spindle	mm/s	0.1 – 0.5	0.5 – 1.2	1.2 – 3	Higher is Worse
DI Water Coolant Temp temperature_coolant	°C	18 – 24	24 – 32	32 – 60	Higher is Worse
Spindle Motor Load load_motor	%	30 – 60	60 – 75	75 – 100	Higher is Worse

4. Deterministic RUL Model (Weighted Degradation)

Base Useful Life: 2,400 operating hours. **Model:** $RUL = BaseLife * (1 - (0.45 * wear_vib + 0.30 * wear_temp + 0.25 * wear_load))$

Parameter	Sensor ID	Unit	Weight	Healthy Limit	Critical Limit	Direction
Spindle Vibration	vibration_spindle	mm/s	0.45	0.4	1.4	HIGHER IS WORSE
Coolant Temp	temperature_coolant	°C	0.30	23	38	HIGHER IS WORSE
Motor Load	load_motor	%	0.25	50	85	HIGHER IS WORSE
TOTAL WEIGHT SUM	-	-	1.00 (100%)	-	-	VERIFIED OK

5. Troubleshooting & Anomaly Symptoms Matrix

Symptom & ID	Severity	Related Sensors	Possible Root Causes	Recommended Corrective Action
Wafer Backside Chipping Exceeds 25µm SYM-WS-001	HIGH	vibration_spindle, load_motor	- Diamond blade edge loading - Spindle bearing vibration harmonic - Feed rate excessive	Dress blade with silicon carbide dressing stick and verify spindle vibration < 0.5 mm/s.
Kerf Width Drift > 5µm SYM-WS-002	MEDIUM	temperature_coolant, pressure_coolant	- Coolant nozzle misalignment - DI water temperature drift - Chuck vacuum leak	Re-align coolant spray nozzle directly on blade tangent and purge vacuum line filter.

6. Authoritative Diagnostic Knowledge Base (Failure Scenarios)

Scenario 1: High-Speed Spindle Harmonic Micro-Spalling (SCEN-WS-001)	Severity: WARNING
Telemetry Sensor Pattern:	vibration_spindle > 1.2 mm/s, load_motor > 70%
Possible Root Causes:	Silicon slurry ingress past labyrinth seal Air-bearing hydrodynamic film breakdown
Recommended Corrective Action:	Replace diamond blade, flush DI coolant circuit, and dynamic-balance spindle rotor.
Verification & Recovery Steps:	Execute LOTO > Inspect spindle runout with dial gauge (< 0.5µm) > Perform 5-wafer test cut and inspect kerf under microscope