

REPORT CLASSIFICATION

Classification Type	Full Form Analysis
---------------------	--------------------

DATE / TIME

Date of Occurrence	2004-12
Local Time Of Day	1801-2400

PLACE

Locale Reference	Airport
Locale	ZZZ.Airport
State	US
Altitude - AGL	0

AIRCRAFT / EQUIPMENT X

Aircraft Operator	Air Carrier
Make Model Name	B737-300
Crew Size	2
Operating Under FAR Part	Part 121
Mission	Passenger
Flight Phase	Parked
Maintenance Status - Maintenance Items Involved	Repair

COMPONENT 1

Aircraft Reference	X
Aircraft Component	Horizontal Stabilizer

PERSON 1

Aircraft Reference	X
Reporter Organization	Air Carrier
Function - Maintenance	Technician
ASRS Report Number	639488
Human Factors	Time Pressure
Human Factors	Troubleshooting

PERSON 2

Aircraft Reference	X
Reporter Organization	Air Carrier
Function - Flight Crew	Captain
Function - Flight Crew	Pilot Flying

PERSON 3

Aircraft Reference	X
Reporter Organization	Air Carrier
Function - Flight Crew	First Officer
Function - Flight Crew	Pilot Flying

EVENTS

Anomaly	Aircraft Equipment Problem - Critical
Anomaly	Deviation / Discrepancy - Procedural - FAR
Anomaly	Deviation / Discrepancy - Procedural - Maintenance
Anomaly	Deviation / Discrepancy - Procedural - Published Material / Policy
Detector - Person	Flight Crew
Result - General	Maintenance Action
Result - General	None Reported / Taken

ASSESSMENTS

Contributing Factors / Situations	Aircraft
Contributing Factors / Situations	Chart Or Publication
Contributing Factors / Situations	Human Factors
Primary Problem	Human Factors

NARRATIVE 1

ON DEC/THU/04, I WAS DOING A WALKAROUND ON ACFT X, WHEN I DID NOT SEE THE SPD TAPE COMING OFF THE L-HAND HORIZ STABILIZER LEADING EDGE. THAT MORNING, THE CREW FOUND THAT THE SPD TAPE HAD BEGAN TO PEEL OFF. I THINK THAT PAYING MORE ATTN TO SPD TAPE AREAS WILL PREVENT THIS FROM HAPPENING AGAIN.

SYNOPSIS

A B737-300 TECHNICIAN RPTS MAKING A WALKAROUND INSPECTION AND MISSING THE SPD TAPE PEELING OFF AN INTERIM REPAIR TO THE L HORIZ STABILIZER LEADING EDGE.

