

REPORT CLASSIFICATION

Classification Type	Full Form Analysis
---------------------	--------------------

DATE / TIME

Date of Occurrence	2012-09
Local Time Of Day	1201-1800

PLACE

Locale Reference	Airport
Locale	ZZZ.Airport
State	US
Altitude - AGL	0

ENVIRONMENT

Light	Daylight
-------	----------

AIRCRAFT / EQUIPMENT X

Aircraft Operator	Air Carrier
Make Model Name	B737-800
Crew Size	2
Operating Under FAR Part	Part 121
Mission	Passenger
Flight Phase	Parked
Maintenance Status - Maintenance Deferred	N
Maintenance Status - Released For Service	N
Maintenance Status - Maintenance Type	Unscheduled Maintenance
Maintenance Status - Maintenance Items Involved	Inspection

COMPONENT 1

Aircraft Reference	X
Aircraft Component	HF SSB
Manufacturer	Boeing

COMPONENT 2

Aircraft Reference	X
Aircraft Component	Vertical Stabilizer/Fin
Manufacturer	Boeing

PERSON 1

Aircraft Reference	X
Location In Aircraft	Flight Deck
Reporter Organization	Air Carrier
Function - Flight Crew	Captain
Qualification - Flight Crew	Air Transport Pilot (ATP)
ASRS Report Number	1036727
Human Factors	Communication Breakdown
Human Factors	Situational Awareness
Communication Breakdown - Party1	Flight Crew
Communication Breakdown - Party2	Maintenance

EVENTS

Anomaly	Aircraft Equipment Problem - Critical
Detector - Person	Flight Crew
When Detected	Pre-flight
Result - General	Flight Cancelled / Delayed
Result - General	Release Refused / Aircraft Not Accepted

ASSESSMENTS

Contributing Factors / Situations	Aircraft
Contributing Factors / Situations	Equipment / Tooling
Contributing Factors / Situations	Human Factors
Primary Problem	Aircraft

NARRATIVE 1

September 2012. During preflight, [crew] discovered erosion tape on the HF antenna peeling off. Contacted Maintenance and entered into logbook. After inspection by Mechanic, and discussion with Captain, it was decided that the best course of action would be to remove peeling tape and defer repair. Mechanic said it would

take one hour to get equipment and effect repair. After about 15-minutes, Mechanic returned and stated repair could not be accomplished at current location due to proximity of taxiway and possible risk of jet blast to [truck] lift from passing aircraft. I stated that they should move aircraft either by taxi or tow and accomplish repair. Approximately one hour later Maintenance Supervisor came to cockpit and stated aircraft was within limits and repairs or removal of tape would not be accomplished. I tried to explain that the tape could possibly come off in flight and blow onto the Elevator Pitot System which is located directly behind the peeling tape area. Supervisor stated that if I wanted to refuse the aircraft that was my prerogative. Captain Y also appeared at the aircraft to investigate the cause of the delay. After explaining my position he conferred with the Maintenance Supervisor and returned advising me to enter reason for refusal into logbook. Entered into logbook and left aircraft. New aircraft found and departed three hours and 44 minutes late. I suggest Maintenance concentrate on repairing discrepancies rather than putting so much effort into figuring out how to defer repairs.

SYNOPSIS

Captain describes his efforts to have Maintenance remove erosion tape from the HF antenna on the vertical stabilizer of a B737-800 aircraft, due to tape was peeling off and potentially cover Elevator Pitot System in flight. Maintenance Supervisor disagreed. Captain refused aircraft.

