

REPORT CLASSIFICATION

Classification Type	Full Form Analysis
---------------------	--------------------

DATE / TIME

Date of Occurrence	2013-10
Local Time Of Day	0001-0600

PLACE

Locale Reference	Airport
Locale	ZZZ.Airport
State	US
Altitude - AGL	0

ENVIRONMENT

Work Environment Factors	Poor Lighting
Light	Night

AIRCRAFT / EQUIPMENT X

Aircraft Operator	Air Carrier
Make Model Name	B737-800
Operating Under FAR Part	Part 121
Flight Phase	Parked
Maintenance Status - Maintenance Type	Scheduled Maintenance
Maintenance Status - Maintenance Items Involved	Inspection

COMPONENT 1

Aircraft Reference	X
Aircraft Component	Fuselage Skin
Manufacturer	Boeing
Problem	Malfunctioning

PERSON 1

Location Of Person	Gate / Ramp / Line
--------------------	--------------------

Reporter Organization	Air Carrier
Function - Maintenance	Technician
Qualification - Maintenance	Airframe
Qualification - Maintenance	Powerplant
ASRS Report Number	1127027
Human Factors	Situational Awareness

EVENTS

Anomaly	Aircraft Equipment Problem - Less Severe
Anomaly	Deviation / Discrepancy - Procedural - Published Material / Policy
Were Passengers Involved In Event	No
Result - General	Maintenance Action

ASSESSMENTS

Contributing Factors / Situations	Aircraft
Contributing Factors / Situations	Human Factors
Contributing Factors / Situations	Procedure
Primary Problem	Procedure

NARRATIVE 1

I work midnight shift at ZZZ airport. On the night I was assigned an A-Check on a B737-800. I performed the General Visual (G/V) walk around inspection on the aircraft. I was informed later on, that an area of corrosion was found on the left aft side of the fuselage, just aft of the lav motor exhaust port. I do not recall noticing evidence of corrosion on my walk around. I started the inspection at the nose of the aircraft and walked down the right side inspecting the fuselage, engine, wing, and gear, around the tail and continued on the left side inspecting fuselage, wing, engine, and gear. Conditions at the time were dark since I work midnight shift and the area of concern was painted gray. I performed my walk around using my flashlight. [Line] Gate.

SYNOPSIS

A Line Aircraft Maintenance Technician (AMT) was informed that corrosion was found on the lower aft fuselage skin, just aft of the Lavatory Motor exhaust port on a B737-800 aircraft. He had previously accomplished an A-Check and walk around inspection on midnight shift using a flashlight.

