

REPORT CLASSIFICATION

Classification Type	Full Form Analysis
---------------------	--------------------

DATE / TIME

Date of Occurrence	2000-02
Local Time Of Day	1201-1800

PLACE

Locale Reference	Airport
Locale	IAH.Airport
State	TX
Relative Position - Distance Nautical Miles	0
Altitude - AGL	0

ENVIRONMENT

Flight Conditions	VMC
Light	Daylight

AIRCRAFT / EQUIPMENT X

ATC / Advisory - Tower	IAH.Tower
Aircraft Operator	Air Carrier
Make Model Name	B737-800
Crew Size	2
Operating Under FAR Part	Part 121
Flight Plan	IFR
Mission	Passenger
Flight Phase	Parked
Number Of Seats	156

PERSON 1

Aircraft Reference	X
Reporter Organization	Air Carrier
Function - Flight Crew	Captain

Function - Flight Crew

Pilot Flying

PERSON 2

Aircraft Reference	X
Reporter Organization	Air Carrier
Function - Flight Crew	First Officer
Function - Flight Crew	Pilot Not Flying
Qualification - Flight Crew	Commercial
Qualification - Flight Crew	Air Transport Pilot (ATP)
Qualification - Flight Crew	Multiengine
Qualification - Flight Crew	Instrument
Experience - Flight Crew Total	21000 hrs
Experience - Flight Crew Last 90 Days	230 hrs
Experience - Flight Crew Type	16500 hrs
ASRS Report Number	463600

PERSON 3

Aircraft Reference	X
Reporter Organization	Air Carrier
Function - Flight Crew	Captain
Function - Flight Crew	Pilot Flying
Qualification - Flight Crew	Air Transport Pilot (ATP)

PERSON 4

Aircraft Reference	X
Reporter Organization	Air Carrier
Function - Flight Attendant	Flight Attendant On Duty
Qualification - Flight Attendant	Current

PERSON 5

Aircraft Reference	X
Function - Flight Attendant	Flight Attendant On Duty
Qualification - Flight Attendant	Current

EVENTS

Anomaly	Aircraft Equipment Problem - Less Severe
---------	--

Anomaly	Deviation / Discrepancy - Procedural - Published Material / Policy
Anomaly	Other: Tail Skid Damage
Detector - Person	Flight Crew
Result - General	Maintenance Action
Result - General	None Reported / Taken

ASSESSMENTS

Contributing Factors / Situations	Aircraft
Contributing Factors / Situations	Human Factors
Primary Problem	Human Factors

NARRATIVE 1

DURING WALKAROUND THE NEXT CREW IDENTED THE BUMP (DIMPLE) ON THE TAILSKID ON B737-800 HAD DAMAGE (SLIGHT SCRAPE ON PAINT). THE TAILSKID INDICATOR SHOWED NO COMPRESSION OR INDICATION OF GND CONTACT. WE HAD FLOWN THE ACFT FOR 2 LEGS. FO HAD SEEN NO DAMAGE DURING HIS WALKAROUND. BOTH OF OUR LNDGS WERE MADE AT FLAPS 40 DEGS TO MINIMIZE TAILSKID STRIKE OCCURRENCE. I ASKED BOTH FLT ATTENDANTS SITTING IN REAR OF ACFT, IF THEY HEARD A SCRAPING DURING ANY TKOF OR LNDG. THEY BOTH SAID NO. I BELIEVE THE DAMAGE WAS DONE PRIOR TO MY TAKING THE ACFT AND THAT FO JUST MISSED IT ON HIS WALKAROUND.

SYNOPSIS

SLIGHT TAILSKID DAMAGE DISCOVERED ON B737-800.

