

REPORT CLASSIFICATION

Classification Type	Full Form Analysis
---------------------	--------------------

DATE / TIME

Date of Occurrence	2007-04
Local Time Of Day	1201-1800

PLACE

Locale Reference	Airport
Locale	SFO.Airport
State	CA
Relative Position - Distance Nautical Miles	0
Altitude - AGL	0

ENVIRONMENT

Flight Conditions	VMC
Light	Daylight

AIRCRAFT / EQUIPMENT X

Aircraft Operator	Air Carrier
Make Model Name	B737-500
Crew Size	2
Operating Under FAR Part	Part 121
Flight Plan	IFR
Mission	Passenger
Flight Phase	Parked

PERSON 1

Aircraft Reference	X
Reporter Organization	Air Carrier
Function - Flight Crew	Captain
Function - Flight Crew	Pilot Flying
Experience - Flight Crew Total	10000 hrs

Experience - Flight Crew Last 90 Days	200 hrs
Experience - Flight Crew Type	6000 hrs
ASRS Report Number	734733

EVENTS

Anomaly	Aircraft Equipment Problem - Less Severe
Detector - Person	Flight Crew
Result - General	None Reported / Taken

ASSESSMENTS

Contributing Factors / Situations	Aircraft
Primary Problem	Aircraft

NARRATIVE 1

ONCE AGAIN, ANOTHER B737 WITH PAINT PEELING IN THE CRITICAL RVSM AREA, CAUSING IT TO HAVE THE CF LIMITATION OF FL280 AND BELOW. THIS CREATES ADDITIONAL PREFLT DUTIES AND LIMITS THE EFFICIENCY OF THE OP. IT CAN CAUSE POTENTIAL SAFETY ISSUES ASSOCIATED WITH ICING, TURB AND CONVECTIVE ACTIVITY. THESE ISSUES DID NOT AFFECT THIS FLT, BUT HAVE IN THE PAST WITH ANOTHER ACFT NON-RVSM, DUE TO PAINT PEELING. ONE ACFT HAS HAD THIS LIMITATION SINCE MAR/XA/07. THE APPEARANCE OF OUR ACFT IS NON-PROFESSIONAL AND DOESN'T REPRESENT QUALITY AND SAFETY. THE PAINT ISSUE NEEDS TO BECOME AN OPERATIONAL AND SAFETY PRIORITY.

SYNOPSIS

B737 CAPTAIN NOTES ACFT WITH PEELING PAINT CAUSING NON-RVSM STATUS.

