Welcome

After DFT insert you need signoff , corners, derate, checks, ECO, tapeout gates, markers

The idea

- Toy tiny_signoff

Two tracks

- Implement track uses common/ solvers; browser lab track uses platform tools

Toy design

- Tiny_signoff: 3 corners, ss derate=1.1, fail_count=2, 2 ECOs, tapeout after ECO

Path

- Corners → signoff corner → derate → checks → ECO → apply → tapeout → markers → engine

Begin

- Next: list PVT corners