

Lab Report

Date: May 15th, 2026

Written by: Yongyu Xu

Team: E1

Team Members

Last name	First name	Email
Rahman	Md Mahbubur	md-mahbubur.rahman@stud.hshl.de
Sakib	Md Naimur Rahaman	md-naimur-rahaman.sakib@stud.hshl.de
Xu	Yongyu	yongyu.xu@stud.hshl.de
Koluacik	Baris	baris.koluacik@stud.hshl.de

Goal

Assemble the vehicle and test the sensors to ensure they are functioning properly.

Discussion

1. The motor is being pushed by a screw, but this has little effect, as shown in Figure 1.




Figure 1 The Motor Holder

2. The IR-Sensor Holders were not sturdy enough and broke during installation, it has been reprinted.
3. The chassis is too close to the ground, but no issues have been observed so far, as shown in Figure 2.




Figure 2 The chassis and ground

4. Both the IR-Sensors and the Ultrasonic-Sensors are functioning properly, please refer to the videos in the folder for details.