ABB	Software Design Review			S	SDR	
Responsibility:	Date:	Language:	Filing system :	Revision:	Page:	
Instruments		en	-	-	1/2	
Template Issued by:	Template Approved:		Template Released:	Are	a of validity:	
A. Stelter	PSM AP2.2		10/2004	Al	PR/I	

Project:	NV_mem
Document under Review:	Software Design Description NV-Handler IIMS_V2_1
Revision:	2.1
Review Date:	29-06-2009

Review-Participant:

Place	Dept.	Name	
Bangalore	INCRC	Ashwin Herur R	
Bangalore	INCRC	Ganapathi R	

Decision of the Review:

Decision	next steps
☐ Inspection passed <i>without restrictions</i>	Phase finished
■ Inspection passed <i>with restrictions</i>	some changes must be done
☐ Inspection <i>not</i> passed	Inspection must be repeated

Changes are proved: The Reviewer confirms that all changes are done:

proved Rev:	Date:	Reviewer:
2.2	10-07-2009	Ashwin Herur R

Check list:

		yes	no
1.	Is the software architecture distinct and documented?	Υ	
2.	Fit the modules together?	Υ	
3.	Are complex algorithms/procedures explained?	Υ	
4.	Is a strategy for error handling designated?	Υ	
5.	Is the configuration management system well prepared?	Υ	
6.	Are all open issues transferred to the defects table?	Υ	

Remarks:

ABB	Software Design Review		Si	SDR	
Responsibility:	Date:	Language:	Filing system :	Revision:	Page:
Instruments		en	-	-	2/2
Template Issued by:	Template Approved:		Template Released:	Area	of validity:
A. Stelter	PSM AP2.2		10/2004	AP	R/I

Defects

No.	Check	Description	Major	done
	point		defect	Date
1		Document name has no numbering	N	No Action
		Answer: the document is an external document (Minden), so it a part of an external package of documents called 266_FE_NV_MEM		
2		Area of Validity need to be checked	N	No Action
		Answer: the document is an external document (Minden),		
		area of validity is referred to Germany		
3		Acronyms need to be added.	Υ	
4		4.2.3 Conclusion: starts with Sl. No. 2, Number 1 is missing.	Υ	09/07/2009
5		4.3 Protocol SPI-Bus is not applicable for MiLe2. So it can be deleted or the design should be customized for different project.	N	09/07/2009
6		4.6.1 I ² C-Bus via interrupt or polling: 1 Byte is given as 9 bits. Please check	N	09/07/2009
		Answer: modified in 8 bits + Acknowledge		
7		Page 23 is left blank.	N	09/07/2009
		5.3 Static Modeling: Mismatch in the methods in code and Class Diagram.	Υ	09/07/2009
8		5.5.6 Load: in the flow chart what is Task-Wechsel?	N	09/07/2009
9		For the Functions CpyPageToPage, FileToNV,InitializeNV, CheckRam, Save, Load, Format etc use return instead of end in the flow charts.	N	09/07/2009
10		Class design missing for NV_Service.	Υ	09/07/2009
11		Sequence diagrams can be added to show the Read and Write operations to NV.	N	No Action
		Answer: too complex to be in only one diagram		