

System x Distributed Power Interconnect (DPI) PDU Firmware Change History

Note: This firmware change only affects the following part number DPI PDU's: 42R8743, 44V3897, 00AK193, 40K9637, 40K9638, 40K9639, 39M2816, 39M2817.

PDU Release notes for Production Firmware Version 2.16.0002 (Previous Firmware Version 2.14.0003)

- 1.) For SP4 PDU's in table listed below, change part numbers from old part number to new part number in the PDU GUI web page, per OEM request.

Note: This firmware change only affect Old part number units listed below.

Old Part Number	New part number
00AK193	39M2816
40K9637	00AK194
40K9638	46W1590
40K9639	46W1592
39M2817	44X3193

PDU Release notes for Production Firmware Version 2.14.0003 (Previous Firmware Version 2.12.0001)

- 1.) For DPI PDU's in table listed below, change part numbers from old part number to new part number in the PDU GUI web page.

Note: This firmware change only affect Old part number units listed below.

Old Part Number	New part number
42R8743	00FW787
44V3897	00FW789
39M2816	00AK193

PDU Release notes for Production Firmware Version 2.12.0001 (Release date of 11/05/2013) (Previous Firmware Version 2.10.0001)

- 1.) Changed kernel to puffer 5514.10030.
- 2.) Upgraded firmware from V0210.0001 to V0212.0001 to support new kernel.

PDU Release notes for Production Firmware Version 2.10.0001 (Release date of 5/14/2009) (Previous Firmware Version 2.08.0011)

- 1.) Modify the existing part number display rule. If Part Number is "39M2817" or "43V6045", the GUI will display "Kit P/N 43V6045 (Option P/N 39M2817)". This change does not affect any other models or part numbers.
- 2.) Fixed 0xd0 command of FW version to properly report the correct FW version.

PDU Firmware Version 0208.0011 Release Notes

Previous Production Firmware – 0206.0007

- 1.0 Enhancements
 - 1.1 Modified Upload button change to hyperlink & modified Help file
 - 1.2 Modified the driver D1 and D0 of command format because the SNMP card can setup date format
 - 1.3 Added Statistics function in MIB file
 - 1.4 Added Statistics function for SNMP
 - 1.5 Added SLP function.
 - 1.6 Added new model "39M2817"
 - 1.7 Web page font size setting via user's web browser
 - 1.8 Added SNMPv3
 - 1.9 Increase description field to 256
 - 1.10 Modified the Help menu for the Power Management -> Statistics -> Overall PDU web page as shown in the embedded document
 - 1.11 Modified in the Help menu for external links, include what the maximum number of characters a link is allowed to be
 - 1.12 Modified the range of refresh rate is 4~600 seconds
 - 1.13 Modified the auto refresh function when change SNMPv1 and SNMPv3
 - 1.14 Modified if a user tries to change his or her access from Read/Write to Read Only, add a pop-up prompt that asks them if they are sure that they want to change their access to read only
 - 1.15 Added new model "40K9637","43V5995","44V3897","40K9639","42R8744"
- 2.0 Problem Fixes
 - 2.1 Fixed Output Current Min value for SNMP
 - 2.2 Modified "FLASH_PARAM_LENGTH" 0x2000 -> 0x4000 and changed "FLASH_BACKUP_ENTRY" 0xFC20 -> 0xFD40, "FLASH_TEMP_ENTRY" 0xFC20 -> 0xFD80, "FLASH_SAVE_ENTRY" 0xFC20 -> 0xFDC0
 - 2.3 Modified SSH issues because buffer overflow
 - 2.4 Modified the SNMP community string rules
 - 2.5 Fixed parameter lost issues that because Outlet Name length "DT_STRING" change to "DT_ULTRALONGSTRING", so the customer want to keep all parameter
 - 2.6 Fixed the SNMPv3 tools connect to device result cold boot issues
 - 2.7 Fixed the Help menu for SNMP V3 screen
 - 2.8 Fixed in IBM DPI status page, the refresh rate is around 5 sec even set the refresh interval to 10 seconds
 - 2.9 Fixed the IP address had a space character at the end of the address and the DPI PDU wasn't handling it correctly
 - 2.10 Modified the Load group descriptions so that line feeds would be accepted and text would appear on the monitor page exactly as it appeared on the configuration page
 - 2.11 Modified the max output voltage displayed in the Load Group 1 page to display the maximum output voltage
 - 2.12 Modified the mib-2 oid 1.3.6.1.2.1.1.5 to update with any and all changes to the System Name
 - 2.13 Modified console and telnet to correct buffer overflow due to outlet name length
 - 2.14 Modified monitor page to correct buffer overflow due to outlet name length

End