

Catalyst Efficiency Code After Software Update

Document: TSB-19-008

Type: Bulletin

Model: Falcon

Published: 2019-08-22

1 Condition

Falcon vehicles set code P0420 following an earlier engine calibration update, with no driveability complaint.

2 Repair Procedure

Apply the revised calibration. Replace catalytic converter CAT-5500 only if efficiency remains below threshold after the update. Oxygen sensor comparison steps are in the Falcon Service Manual, MAN-FAL-3.