

Front Brake Judder After Pad Replacement

Document: TSB-22-031

Type: Bulletin

Model: Heron

Published: 2022-04-02

1 Condition

Heron vehicles return with steering wheel vibration under braking within months of a front pad replacement using brake pad kit BP-7720.

2 Repair Procedure

Replace front rotors BR-7731 in pairs together with brake pad kit BP-7720. Pad-only repairs on worn rotors cause the judder to return. Torque specifications are listed in the Heron Service Manual, MAN-HER-2.