

Battery Drain and Low System Voltage

Document: TSB-23-052

Type: Bulletin

Model: Falcon

Published: 2023-02-17

1 Condition

Falcon vehicles present with code P0562, dim lights at idle, or repeat flat batteries.

2 Repair Procedure

Test alternator ALT-8810 under load before fitting battery BAT-1200. Battery-only repairs do not correct the underlying low-output alternator. The load test procedure is in the Falcon Service Manual, MAN-FAL-3.