

Osprey Service Manual (1st Edition)

Document: MAN-OSP-1

Type: Manual

Model: Osprey

Published: 2021-01-20

1 Electrical

Electrical service for the Osprey platform.

1.1 Wheel Speed Sensor Replacement

Replace wheel speed sensor WSS-3300. Code C0035 indicates left front sensor circuit fault.

1.2 Charging System

Alternator ALT-8810 output test. Code P0562 sets when system voltage is low at idle.

2 Engine

Engine service for the 3.5 V6.

2.1 Misfire Diagnosis

For code P0300 inspect spark plug set SP-1108 and check for intake leaks before component replacement.