

Safety Recall - Ignition Coil Connector Overheating

Document: RC-2021-04

Type: RecallNotice

Model: Falcon

Published: 2021-05-10

1 Defect Description

On certain 2019-2020 Falcon vehicles, the ignition coil IC-2042-A connector can overheat, increasing the risk of an engine compartment fire.

2 Remedy

Dealers will replace the coils with revised ignition coil IC-2042-B and the associated connector free of charge.