

Safety Recall - Brake Hose Abrasion

Document: RC-2022-09

Type: RecallNotice

Model: Heron

Published: 2022-10-05

1 Defect Description

On certain Heron vehicles, the front brake hose BH-7745 can contact the strut bracket, abrading the hose and risking brake fluid loss. Inspection points are described in the Heron Service Manual, MAN-HER-2.

2 Remedy

Dealers will inspect and replace brake hose BH-7745 with a revised routing clip free of charge.