

"Falcon 1.6: P0562 system voltage low from failing alternator"

Document: tsb-22-371

Area: bulletins

1 Condition

Some Falcon 1.6 vehicles may set DTC P0562 (System Voltage Low) with an illuminated charging warning indicator. Drivers typically notice dimming headlamps, slow cranking, and a battery telltale that appears under electrical load. The condition often progresses to a no-start if left unaddressed. The System Voltage Codes section describes the P0562 set criteria in detail.

2 Cause

P0562 is most often caused by a failing alternator ALT-8810 that can no longer maintain charging output above the regulated threshold, which in turn leaves the battery BAT-1200 undercharged. A weak or sulfated BAT-1200 can also pull system voltage low even when ALT-8810 output is marginal. Review the Alternator and Battery descriptions, and confirm the code against the Diagnostic Trouble Codes reference.

3 Repair Procedure

Follow PROC-ALT to verify charging output before condemning the alternator ALT-8810. Begin with the Charging System Diagnosis Procedure to load-test the system and measure regulated voltage. If BAT-1200 fails its capacity test, complete the Battery Replacement Procedure and recheck output. Full system context is available in the Charging System Overview within the Falcon Charging Service Manual .