

Heron HVAC blower motor circuit failure causing inoperative cabin fan

Document: tsb-26-112

Area: bulletins

1 Condition

Affected Heron vehicles may store DTC B1352 (Blower Motor Circuit Failure) with a completely inoperative cabin fan CABF-7280 at all speed settings. The customer typically reports no airflow from the vents regardless of temperature or mode selection. Confirm the fault is circuit-related rather than a blown fuse or control-head issue, and review the Blower Motor and Cabin Air Filter overview before disassembly. The Diagnostic Trouble Codes section lists the B1352 set conditions.

2 Cause

The condition is caused by an open winding in the blower motor BLW-7200, which interrupts current flow and triggers the B1352 fault while leaving cabin fan CABF-7280 inoperative. Thermal cycling and brush wear accelerate the internal failure over time. Refer to the Blower Motor Circuit Code for the precise circuit description, and review the HVAC System Overview to understand how BLW-7200 drives airflow through the system.

3 Repair Procedure

Perform PROC-BLOWER to confirm the open circuit in blower motor BLW-7200 and replace the unit following the HVAC Blower Motor Replacement Procedure in the Air Distribution Sub-System Service section. While the assembly is accessed, inspect and if necessary service the filter using the Cabin Air Filter Replacement Procedure . After replacing BLW-7200, clear B1352 and verify cabin fan CABF-7280 operates at all speeds. For comparison on similar HVAC complaints, the Marlin EV Hvac Service Manual :: HVAC System Diagnosis may provide supplemental guidance.