

Ridgeline HD front strut knock from worn strut assembly

Document: tsb-21-211

Area: bulletins

1 Condition

Affected Ridgeline HD vehicles may exhibit a knocking or clunking noise from the front suspension over bumps and during low-speed maneuvering. The noise originates from front strut assembly STRT-8500 and is most noticeable on rough or uneven surfaces. In some cases drivers also report a slight degradation in ride quality and steering feel. See Ridgeline HD Suspension Service Manual :: Front Strut Assembly to confirm the affected component.

2 Cause

The noise is caused by internal wear within front strut assembly STRT-8500, which develops play in the damper and upper mount over high mileage and heavy-load use. The resulting looseness produces the characteristic knock as the suspension cycles. General suspension context is provided in Ridgeline HD Suspension Service Manual :: Suspension System Overview . A related condition affecting the same corner is described in Ridgeline HD: Front clunk and uneven tire wear from worn lower control arm .

3 Repair Procedure

Replace front strut assembly STRT-8500 in axle pairs following PROC-STRUT, then perform a four-wheel alignment before returning the vehicle. Detailed spring-compression and torque steps are provided in Ridgeline HD Suspension Service Manual :: Front Strut Replacement Procedure and Ridgeline HD Suspension Service Manual :: Front Strut Sub-System Service . For a comparable platform procedure, see Heron Suspension Service Manual :: Front Strut Replacement . A later related bulletin is Ridgeline HD 6.7 TD: Front clunk and uneven ride from worn front strut .