

Marlin EV front brake hose may chafe against suspension component, causing

Document: rc-2022-01

Area: recalls

1 Defect Description

On affected Marlin EV vehicles, the front brake hose BH-7745 can contact a nearby suspension component through the steering range, causing the hose outer layer to chafe and eventually wear through. A compromised BH-7745 can develop a fluid leak that reduces hydraulic pressure to the front brakes. Technicians should inspect the routing and condition of the hose using the Marlin EV Brakes Service Manual :: Hydraulic Lines and Fluid section. Comparable inspection guidance for the front circuit is available in the Vega Brakes Service Manual :: Front Brake Sub-System .

2 Remedy

Dealers will replace the front brake hose BH-7745 with a revised hose featuring corrected routing and additional standoff clearance, following the Marlin EV Brakes Service Manual :: Brake Hose Replacement Procedure . After the hose is replaced, the system must be refilled with brake fluid BF-7790 and bled to remove air per the Marlin EV Brakes Service Manual :: Brake Fluid Flush and Bleed Procedure . Technicians may also reference the equivalent Vega Brakes Service Manual :: Brake Fluid Flush and Bleed and Vega Brakes Service Manual :: Front Brake Hose Replacement procedures for technique. This recall remedy is performed at no charge; see <https://www.nhtsa.gov/recalls> for owner notification details.