

Ridgeline HD lower control arm weld defect may allow separation and loss of

Document: rc-2022-06

Area: recalls

1 Defect Description

Affected Ridgeline HD trucks were built with lower control arms (part CARM-8540) whose front cross-member weld may have been incompletely fused during fabrication. Under sustained suspension loading the deficient weld on CARM-8540 can propagate a crack and ultimately allow the control arm to separate at the mounting point, leading to a sudden loss of steering control. Symptoms preceding failure typically include a pronounced front-end clunk and accelerated, uneven tire wear, as documented in Ridgeline HD: Front clunk and uneven tire wear from worn lower control arm :: Condition . Technicians should review the broader system context in the Ridgeline HD Suspension Service Manual :: Control Arms and Sway Bar Links before beginning any inspection.

2 Remedy

Dealers will inspect and replace the lower control arm CARM-8540 on all affected vehicles at no charge, regardless of the part's apparent condition. Perform the replacement following the Ridgeline HD Suspension Service Manual :: Control Arm Replacement Procedure , torquing all fasteners to the published specification and verifying alignment afterward. The full repair sequence and supporting reference material are contained in the Ridgeline HD Suspension Service Manual , and the related condition report in Ridgeline HD: Front clunk and uneven tire wear from worn lower control arm should be closed out concurrently. Owners of affected vehicles will be notified by mail; recall details are also posted at <https://www.nhtsa.gov/recalls>.