

Safety Recall - Brake Hose Abrasion

Document: RC-2022-09

Type: RecallNotice

Model: Heron

Published: 2022-10-05

1 Defect Description [Ref: S-RC202209-1]

On certain Heron vehicles, the front brake hose BH-7745 can contact the strut bracket, abrading the hose and risking brake fluid loss.

2 Remedy [Ref: S-RC202209-2]

Dealers will inspect and replace brake hose BH-7745 with a revised routing clip free of charge.