

Catalyst Efficiency Code After Software Update

Document: TSB-19-008

Type: Bulletin

Model: Falcon

Published: 2019-08-22

1 Condition [Ref: S-TSB19008-1]

Falcon vehicles set code P0420 following an earlier engine calibration update, with no driveability complaint.

2 Repair Procedure [Ref: S-TSB19008-2]

Apply the revised calibration. Replace catalytic converter CAT-5500 only if efficiency remains below threshold after the update.