

Intermittent Wheel Speed Sensor Faults

Document: TSB-20-087

Type: Bulletin

Model: Heron

Published: 2020-11-30

1 Condition [Ref: S-TSB20087-1]

Heron and Osprey vehicles set intermittent codes C0035 or U0121, often with no fault found on retest.

2 Repair Procedure [Ref: S-TSB20087-2]

Replace wheel speed sensor WSS-3300 and secure the revised harness clip. Do not replace the ABS module for these codes.