

## **Front Brake Judder After Pad Replacement**

Document: TSB-22-031

Type: Bulletin

Model: Heron

Published: 2022-04-02

### **1 Condition [Ref: S-TSB22031-1]**

Heron vehicles return with steering wheel vibration under braking within months of a front pad replacement using brake pad kit BP-7720.

### **2 Repair Procedure [Ref: S-TSB22031-2]**

Replace front rotors BR-7731 in pairs together with brake pad kit BP-7720. Pad-only repairs on worn rotors cause the judder to return.