

Battery Drain and Low System Voltage

Document: TSB-23-052

Type: Bulletin

Model: Falcon

Published: 2023-02-17

1 Condition [Ref: S-TSB23052-1]

Falcon vehicles present with code P0562, dim lights at idle, or repeat flat batteries.

2 Repair Procedure [Ref: S-TSB23052-2]

Test alternator ALT-8810 under load before fitting battery BAT-1200. Battery-only repairs do not correct the underlying low-output alternator.