

Osprey Service Manual (1st Edition)

Document: man-osp-1

Area: manuals

1 Engine

Service coverage for the Cascadia Osprey 3.5 V6.

1.1 Misfire Diagnosis

The 3.5 V6 sets P0300 for random misfire across banks. Coil-on-plug ignition is shared in concept with the Falcon; the diagnostic flow in the Falcon Misfire Diagnosis applies, but the Osprey uses a different coil and the SP-1108 spark plug set is not compatible. Confirm both banks before condemning components.

1.2 Catalyst Efficiency

P0420 on the V6 is bank-specific. As with the Falcon, rule out misfire before replacing CAT-5500; an ECM-9901 update may apply (see Updated Catalyst Monitor Calibration).

2 Brakes

2.1 Front Brake Service

The Osprey shares the BP-7720 front pad kit and BR-7731 rotor pair with the Falcon. The judder bulletin Brake Judder After Front Pad Replacement applies to both platforms.

3 ABS

3.1 Wheel Speed Sensors

The Osprey uses the same WSS-3300 wheel speed sensor. Code C0035 and the harness routing concern in Wheel Speed Sensor Harness Chafing apply.