

Safety Recall - Ignition Coil Connector Overheating

Document: rc-2021-04

Area: recalls

1 Defect Description

On certain 2019-2020 Falcon vehicles with the 2.0T engine, the ignition coil IC-2042-A connector can overheat under repeated heat cycles, which may lead to a misfire (P0301) and, in rare cases, a thermal event.

2 Remedy

Dealers will install the revised coil IC-2042-B at no charge. For the full replacement procedure see Ignition Coil Replacement , and for the superseding service guidance see TSB-21-114 . Owners can check recall status at NHTSA .