

Safety Recall - Wheel Speed Sensor Harness Chafing

Document: rc-2022-09

Area: recalls

1 Defect Description

On certain Falcon and Osprey vehicles, the front wheel speed sensor WSS-3300 harness can chafe against the brake hose BH-7745 routing, setting code C0035 and, if it shorts, ABS communication loss U0121.

2 Remedy

Dealers will inspect and re-route the WSS-3300 harness and replace it if chafed, at no charge. Diagnose any stored faults per ABS Module Diagnosis and Wheel Speed Sensors . Owners can check recall status at NHTSA .