

Residential Condition Report

AI-populated draft created from a recorded property walkthrough, live transcript, site notes and photo evidence. Prepared for customer demonstration purposes.

Property	42 Park Lane, London
Report type	Residential Condition Report
Survey date	5 June 2026
Prepared for	Acme Property Services
Surveyor	Zain Malik
AI input sources	Audio transcript, room notes, photo evidence

Executive summary

AI FILLED

The property is generally well presented internally. No significant structural cracking was observed from the recorded walkthrough. Minor maintenance items were identified in the kitchen and bathroom, both suitable for routine follow-up rather than immediate urgent action.

Sources: 4 transcript excerpts

High confidence

Key defects and maintenance

AI FILLED

Kitchen: minor staining near the rear window reveal, likely condensation. Bathroom: extractor fan is noisy and should be checked. Living room and bedrooms appear in good decorative order from the available notes.

Sources: audio + photo slots

Needs photo check

Room-by-room findings

Room	Observed condition	AI action
Kitchen	Minor staining near rear window reveal. No further kitchen defects recorded.	Monitor and add photo evidence.
Bathroom	Extractor fan reported as noisy during survey recording.	Recommend service check.
Living room	Generally well presented. No significant visible cracking mentioned.	No action.
Bedrooms	Good decorative order from walkthrough notes.	No action.

Evidence gallery






Photo placeholders demonstrate where captured site images would be automatically linked to the relevant room and defect sections.

AI audit trail

The report keeps the surveyor in control by showing what the AI used, what it inferred, and what still needs review before issue to the client.

Template block	AI instruction	Status
Executive summary	Summarise overall condition in professional surveyor tone.	Accepted draft
Room findings	Extract room names, condition, defects and urgency from audio.	Review required
Defects list	Prioritise observed defects and recommend next actions.	Needs photo
Evidence gallery	Attach photos to matching issues and rooms.	Pending images

Transcript excerpts used

Kitchen has minor staining near the rear window, likely condensation rather than penetrating damp.

Bathroom extractor fan is noisy and should be checked during routine maintenance.

Living room and bedrooms are generally well presented with no significant visible cracking.

Recommend monitoring the kitchen window reveal and adding photographic evidence to the defects section.

Surveyor approval	Client issue
Reviewed and approved by: _____	Issued to: _____
Date: _____	Date: _____