

HUMAN PERFORMANCE PRE-JOB BRIEFING



DATE & TIME	06/01/2026	SHIFT	B
Task Leader	Hussain	SA ID	SA100857
Printed RA/SOP No./Title	sampling Furnace SOP-193	Signature	[Signature]
HIGHEST RISK TASK OF THE DAY (Describe what you will do today):	Take sample from Furnace C		
LOCATION	Furnaces Area		


ERROR TRAPS VS HUMAN PERFORMANCE TOOLS

DISCUSS ALL AND CHOOSE MINIMUM OF TWO ERROR TRAPS AND THEIR CORRESPONDING HUMAN PERFORMANCE TOOLS
(FOR EACH ERROR TRAPS, IT COULD BE MORE THAN ONE HUMAN PERFORMANCE TOOLS)

ERROR TRAPS		HUMAN PERFORMANCE TOOLS	
Time Pressure	☒	☒ STAR (Stop-Think-Act-Review)	
Destruction/interruption/Organization Conflict	☐	☐ Three -Way Communication	
Fatigue / Low Alertness	☐	☐ Self-Check	
Overconfidence / Complacency	☒	☐ Stop-Work Authority/ Stop When Unsure	
Poor Communication	☐	☐ Task Preview / Pre-Job Briefs	
Lack of Knowledge/Experience /Training	☐	☐ Peer Check (Second Check)	
Unclear or Missing Procedures	☐	☐ Use written procedure	
Unverified Assumptions	☐	☐ Post-Job Review / Lessons Learned Questioning Attitude (Continuously asking "What could go wrong?")	
Stress / Pressure from Others	☐	☐ Effective Handover / Briefings	
Unclear Responsibility	☐	☐ Place-Keeping Tools	
Adverse Environment Condition	☐	☐ Independent Verification	
High workload / Multi-tasking	☒	☐ Time out/Pause for Safety	
Unexpected Condition/Equipment Multi-function Condition	☐	☒ High Work Load Redistribution	
Confusing Control/Display	☐	☒ Task Participation and Planning	
Inaccurate Risk Perception	☐		
Emotional Reaction	☐		

PLEASE CHOOSE ONE ERROR / PERFORMANCE MODE

(Please tick the box near the selected performance mode)



HUMAN PERFORMANCE PRE-JOB BRIEFING



CRITICAL STEPS	RISKS
Open the Furnace door	expose to heat
put the sample into the furnace	Burnt +
pour the metal in sample mould	Burnt +

STOP & SEEK OUT CRITERIA	VERIFIED AT FIELD
Wear Full PPE + PPC (hot metal)	Done
- Wear hot metal gloves	Done
- No task should be done on the same Furnace (one task)	Done
- spoon preheating + mould preheating	Done
- put the sample in cold water	Done

EVERYBODY HAS THE RIGHT AND OBLIGATION TO STOP THE WORK WHEN UNSAFE

STOP WHEN UNSURE

☐ I ACKNOWLEDGE THAT I WILL STOP WORK IF IT IS UNSAFE AND I WILL REPORT ANY ABNORMALITY TO MY SUPERVISOR

TEAM MEMBER	NAME	Abdullah Alkalbani	SA ID	100740	SIGNATURE	[Signature]
	NAME	Khair	SA ID	101569	SIGNATURE	[Signature]
	NAME	Shabib	SA ID	101485	SIGNATURE	[Signature]
	NAME	HUSSAIN	SA ID	SAC916834	SIGNATURE	[Signature]
	NAME	Tayyab Ahmad	SA ID	SA929400	SIGNATURE	[Signature]
	NAME	Sumaga Alkinati	SA ID	SA100857	SIGNATURE	[Signature]
	NAME	Mohammed Al-Washati	SA ID	100299	SIGNATURE	[Signature]

WHAT IS THE WORST THING THAT COULD HAPPEN DURING THE EXECUTION OF THE TASK?

Metal explosion.

LESSONS LEARNED

Always ensure one task only in the furnace and preheating should apply before start the process

POST WORK OBSERVATION

DOES THE SOP/RISK ASSESSMENT ADEQUATELY COVER THE TASK REQUIREMENTS	HAS THE TASK BEEN STOPPED AS A RESULT OF STOP CRITERIA?
☒ YES ☐ NO IF NO, TALK TO YOUR LEADER TO UPDATE SOP/RA	☐ YES ☒ NO IF YES, THEN WHAT WAS THE STOP CRITERIA