

Gearbox Failure Investigation Report

Failure Date: January 2026

Observed Symptoms:

- High vibration
- Oil leakage
- Elevated temperature

Root Cause:

Bearing wear caused shaft misalignment.

Corrective Actions:

- Bearing replacement
- Gear inspection
- Alignment correction

Lessons Learned:

Increase vibration monitoring frequency.