

Motor Overheating Investigation

Failure Summary:

Motor temperature exceeded 95°C.

Observed Conditions:

- Reduced cooling airflow
- Bearing friction
- High current draw

Root Cause:

Cooling fan malfunction.

Corrective Actions:

- Replace cooling fan
- Inspect bearings
- Verify electrical load

Preventive Measures:

Monthly cooling system inspection.