

Motor Inspection SOP

Inspection Checklist:

- Check winding temperature.
- Measure vibration.
- Inspect bearings.
- Verify cooling fan operation.
- Check lubrication.

Alarm Limits:

Temperature > 85°C

Vibration > 6 mm/s

Corrective Actions:

Replace bearings. Improve cooling. Balance rotor. Inspect alignment.