

CCM Failure Report

CCM Failure Report 2024 Equipment: CCM Segment Bearing Symptoms: High vibration Abnormal noise Increasing temperature Root Cause: Lubrication failure. Impact: 12 hours downtime. Recommendation: Improve lubrication monitoring. Install predictive vibration monitoring. Maintain spare bearing stock.