

Maple Street Bridge Structural Inspection Report 2026

Structural Defect: Micro-fractures detected in pier support beam 3 due to riverbed scouring. Estimated cost overrun: ,000 USD.