

Inspection request

Requested examination: radiography of two vessel welds

CLIENT

Havenmeer Process Works

CLIENT CONTACT

Bram - Maintenance manager

EXAMINATION LOCATION

Workshop 2 - vessel V-2

REQUESTED DAY

Thursday - start time to be agreed


AVAILABILITY

Contact reachable throughout the work

ATTACHMENTS

Drawing V2-GA rev C; project requirements

WELD LOCATION



Side elevation - both welds run around the full circumference

Weld / drawing ID	Material	Diameter	Wall thickness	Extent requested
7 / W-07	Carbon steel	1,200 mm	12 mm	100%
8 / W-08	Carbon steel	1,200 mm	12 mm	100%

100% means the full circumference of each listed weld.

LOCATION INFORMATION FOR REVIEW

Vessel anchored to supports and connected to pipework. Moving it to a bunker is not a simple transport operation. The proposed irradiation location still requires assessment and acceptance.

Radiography justification

Client preparation - reasons and supporting references

CLIENT / CONTACT

Havenmeer Process Works / Bram

JOB REFERENCE

HM-RT-026 / V-2

01 TECHNIQUE

Why is radiography requested for this type of assignment? Identify the applicable basis and supporting assessment. Include the relevant reference and the person competent in the testing techniques.

02 IRRADIATION LOCATION

Document the assessment of a bunker and of irradiation infrastructure. Explain the proposed location and attach the required risk information. The fixed vessel is job information, not an approval of the hall.

PREPARED BY / FUNCTION

SUPPORTING DOCUMENTS

Task risk analysis

Workshop 2 - information for client and NDT coordination

PARTICIPANTS

Bram / client safety team / NDT company

Identify hazards during the task, agree the protective measures and record who will implement them. The entries below are issues to resolve before work is authorised.

Situation	Hazard to assess	Coordination to agree	Status
Equipment setup	Forklifts pass the vessel.	How will traffic be separated from the work?	OPEN
Nearby workbenches	Other people may approach the work area.	Who will stop nearby work and control access?	OPEN
Radiography	Exposure to ionising radiation.	NDT company: radiation-risk assessment and protective measures.	OPEN

AGREED ACTIONS / PERSON RESPONSIBLE / VERIFICATION

Task hazards are distinct from justification of the examination method and from assessment of the consequences of undetected fabrication defects.