


PRODUCTION PERFORMANCE & QUALITY REPORT

Facility: Main Manufacturing Plant Reporting Period: Weekly Summary

Executive Summary:

There are 4 work orders with a total planned quantity of $111111.0 + 1000.0 + 2.0 + 888888.0 = 1000001.0$ units and a total completed quantity of $0.0 + 1000.0 + 0.0 + 0.0 = 1000.0$ units. The overall completion rate is $1000.0 / 1000001.0 = 0.01\%$. Two work orders are in 'Planned' and 'Draft' status, one is 'Completed', and one is 'Cancelled'.

1. Weekly Production Trends



Production Analysis:

Analysis of actual work order records from the data shows that only one work order (WO202608030002) has been completed with a quantity of 1000.0 units, while the other work orders are either planned, drafted, or cancelled.

Day	Target	Actual	Status
WO202608030001	111111.0	0.0	Below Target
WO202608030002	1000.0	1000.0	On Track
WO202608100001	2.0	0.0	Below Target
WO202608100002	888888.0	0.0	Below Target

2. Machine Performance (OEE Breakdown)

OEE Overview:

No CapacityAnalysis data is available to analyze machine utilization.

[Chart Missing]

Line	OEE Score	Status
------	-----------	--------

3. Rejection vs. Production Volume by Shift

[Chart Missing]

Shift Efficiency Analysis:

No WeighingMachine data is available to analyze shift-wise production.

Shift	Output	Rejections	Defect Rate
-------	--------	------------	-------------

4. Scrap Analysis & Waste Distribution

Key Scrap Drivers:

No Scrap data is available to analyze scrap causes.

[Chart Missing]

5. Corrective Action Plan

Action Item	Target Area	Owner	Deadline
Investigate the cause of low completion rate	Production Team	Operations Department	2026-08-31
Review and revise the production planning process	Planning Team	Operations Department	2026-09-15