


PRODUCTION PERFORMANCE & QUALITY REPORT

Facility: Main Manufacturing Plant Reporting Period: Weekly Summary

Executive Summary:

The production summary shows 1 completed work order with 1000 units, and a total of 4700 units produced in the morning shift. The machine utilization is optimal for machine 1 with 115% utilization. The scrap analysis shows a total of 123 units scrapped, with the highest percentage being 42% for material. The rejection analysis shows a total of 250 units rejected, with the highest percentage being 50% for reason.

1. Weekly Production Trends



Production Analysis:

The production analysis shows that 1 work order is completed with 1000 units, and 3 work orders are in planned, cancelled, or draft status. The total planned quantity is $111111 + 2 + 8888888 = 9000001$ units, and the total completed quantity is 1000 units.


Day	Target	Actual	Status
139	1000	1000	On Track
138	111111	0	Below Target
140	2	0	Below Target
141	8888888	0	Below Target

2. Machine Performance (OEE Breakdown)


OEE Overview:

The OEE overview shows that machine 1 has an optimal utilization of 115%, machine 2 has a utilization of 80%, and machine 3 has a utilization of 95%.

Line	OEE Score	Status
1	115.0%	Optimal
2	80.0%	Below Target
3	95.0%	On Track
6	110.0%	Optimal
8	80.0%	Below Target



3. Rejection vs. Production Volume by Shift



Shift Efficiency Analysis:

The shift analysis shows that the morning shift has produced 4700 units, with 50 units rejected and 20 units scrapped. The defect rate is 1.1%.

Shift	Output	Rejections	Defect Rate
Morning Shift	4700	50	1.1%

4. Scrap Analysis & Waste Distribution

Key Scrap Drivers:

The scrap drivers analysis shows that the total scrap quantity is 123 units, with the highest percentage being 42% for material.

Scrap Distribution by Cause (%)



5. Corrective Action Plan

Action Item	Target Area	Owner	Deadline
Improve material quality	Material	Production	2024-03-01
Reduce rejection rate	Rejection rate	Quality	2024-03-15