


# PRODUCTION PERFORMANCE & QUALITY REPORT

Facility: Main Manufacturing Plant    Reporting Period: Weekly Summary

## Executive Summary:

The production has completed 1000 units out of a planned 111111 units. The overall production is below target, with a completion rate of 0% for most work orders. However, one work order has been completed with a 100% completion rate. The total scrap quantity is 90 units, and the total rejected quantity is 250 units.

## 1. Weekly Production Trends



### Production Analysis:

Analysis of actual work order records from the data shows that most work orders are either planned or cancelled, with only one work order completed. The completed work order has a planned quantity of 1000 units and an actual completed quantity of 1000 units.


| Day | Target   | Actual | Status       |
|-----|----------|--------|--------------|
| 139 | 1000.0   | 1000.0 | On Track     |
| 138 | 111111.0 | 0.0    | Below Target |
| 140 | 2.0      | 0.0    | Below Target |
| 141 | 888888.0 | 0.0    | Below Target |

## 2. Machine Performance (OEE Breakdown)


### OEE Overview:

Analysis of machine utilization from CapacityAnalysis data shows that the overall equipment effectiveness (OEE) is below 85% for most machines. The machine with the highest OEE is Machined 3, with an OEE of 90%.

| Line | OEE Score | Status       |
|------|-----------|--------------|
| 1    | 85.0%     | Optimal      |
| 2    | 75.0%     | Below Target |
| 3    | 90.0%     | Optimal      |
| 6    | 100.0%    | Optimal      |
| 8    | 90.0%     | Optimal      |



## 3. Rejection vs. Production Volume by Shift



**Shift Efficiency Analysis:**


Analysis of shift-wise production from WeighingMachine data shows that the total output is 11750 units, with a total rejection of 225 units. The defect rate is 1.9%.

| Shift   | Output | Rejections | Defect Rate |
|---------|--------|------------|-------------|
| Shift 1 | 4700.0 | 50.0       | 1.1%        |
| Shift 2 | 0.0    | 20.0       | 100.0%      |
| Shift 3 | 1900.0 | 10.0       | 0.5%        |
| Shift 4 | 0.0    | 15.0       | 100.0%      |
| Shift 5 | 500.0  | 100.0      | 20.0%       |
| Shift 6 | 1450.0 | 25.0       | 1.7%        |
| Shift 7 | 700.0  | 5.0        | 0.7%        |

4. Scrap Analysis & Waste Distribution

**Key Scrap Drivers:**

Analysis of scrap causes from Scrap table data shows that the total scrap quantity is 90 units.



5. Corrective Action Plan

| Action Item                                                     | Target Area                    | Owner              | Deadline   |
|-----------------------------------------------------------------|--------------------------------|--------------------|------------|
| Improve production planning to reduce scrap and rejection rates | Production Planning Department | Production Manager | 2024-03-31 |
| Implement quality control measures to reduce defect rate        | Quality Control Department     | Quality Manager    | 2024-04-15 |

|                                                              |                       |                    |            |
|--------------------------------------------------------------|-----------------------|--------------------|------------|
| Provide training to operators to improve machine utilization | Operations Department | Operations Manager | 2024-05-01 |
|--------------------------------------------------------------|-----------------------|--------------------|------------|