


PRODUCTION PERFORMANCE & QUALITY REPORT

Facility: Main Manufacturing Plant Reporting Period: Weekly Summary

Executive Summary:

The manufacturing database contains a total of 29 machine records across various categories and locations, with 10 detailed machine records in the secondary inventory. Machines such as MIG Welder #1 and Auto Assembly Line exhibit high utilization rates at 90.0% and 95.0% respectively. Maintenance and operational statuses vary across the facility, requiring targeted oversight for idle or underperforming units.

1. Weekly Production Trends



Production Analysis:

The production analysis evaluates active machine records and utilization metrics from the available dataset. Equipment like CNC Lathe #1 and #2 maintain efficiency ratings of 85.0% and 88.0% respectively, operating within Building A. Automated systems such as the Auto Assembly Line demonstrate robust performance with a 95.0% utilization rate.


Day	Target	Actual	Status
CNC-001	100	75	Below Target
CNC-002	100	82	Below Target
CNC-003	80	68	Below Target
WLD-001	50	90	On Track
WLD-002	40	65	On Track

2. Machine Performance (OEE Breakdown)

OEE Overview:

Machine utilization varies significantly across the plant floor, ranging from 0.0% for units under maintenance like CNC-004 to a high of 95.0% for the Auto Assembly Line. Equipment in Building A and Building B generally maintain moderate to high utilization, while several units in idle or maintenance status require review.

Line	OEE Score	Status
CNC Lathe #1	75.0%	Below Target
CNC Lathe #2	82.0%	Below Target
CNC Mill #1	68.0%	Below Target
MIG Welder #1	90.0%	Optimal
TIG Welder #1	65.0%	Below Target
Assembly Station #1	88.0%	Optimal
Assembly Station #2	72.0%	Below Target
Auto Assembly Line	95.0%	Optimal
Paint Booth #1	55.0%	Below Target



3. Rejection vs. Production Volume by Shift

[Chart Missing]

Shift Efficiency Analysis:

Shift distribution spans across Shift A, Shift B, and Shift C, capturing diverse operational windows. Shift A hosts primary high-efficiency assets including CNC Lathe #1 and the Auto Assembly Line, whereas Shift B and C manage secondary operations and maintenance windows.

Shift	Output	Rejections	Defect Rate
-------	--------	------------	-------------

4. Scrap Analysis & Waste Distribution

Key Scrap Drivers:

Scrap causes and defect distributions are currently unassigned in the provided machine parameter tables, requiring direct quality logging implementation.

[Chart Missing]

5. Corrective Action Plan

Action Item	Target Area	Owner	Deadline
-------------	-------------	-------	----------

Investigate and resolve maintenance holds for CNC-004 and Haas models	CNC Machining	Maintenance	2023-11-15
Review low utilization rates for Paint Booth #1 and TIG Welder #1	Finishing & Welding	Operations	2023-11-20
Standardize naming conventions and data entry for anomalous machine records	Plant Floor	Data Management	2023-11-30