



B1 (best)   q=2.83, slit len 0.000, slit r 0.29

net area 250.00 cm². How to cut: tape this sheet UNDER the clear plastic (or on top for opaque sheet).
1. Cut along the centre of the black outline. 2. Knife-cut the red slits exactly between the end ticks (no material removed).
3. Punch the 6 blue crosshairs (line points), keep >= 3 mm from the edge. 4. Write the code on the canopy.

50 mm: measure this after printing

100 mm: measure this after printing

Print at 100% / Actual size (NOT 'fit to page').




B2 (best)   q=2.77, slit len 0.066, slit r 0.65

net area 250.00 cm². How to cut: tape this sheet UNDER the clear plastic (or on top for opaque sheet).
1. Cut along the centre of the black outline. 2. Knife-cut the red slits exactly between the end ticks (no material removed).
3. Punch the 6 blue crosshairs (line points), keep >= 3 mm from the edge. 4. Write the code on the canopy.

50 mm: measure this after printing

100 mm: measure this after printing

Print at 100% / Actual size (NOT 'fit to page').




B3 (best)   q=2.92, slit len 0.065, slit r 0.46

net area 250.00 cm². How to cut: tape this sheet UNDER the clear plastic (or on top for opaque sheet).
1. Cut along the centre of the black outline. 2. Knife-cut the red slits exactly between the end ticks (no material removed).
3. Punch the 6 blue crosshairs (line points), keep >= 3 mm from the edge. 4. Write the code on the canopy.

50 mm: measure this after printing

100 mm: measure this after printing

Print at 100% / Actual size (NOT 'fit to page').




B4 (best)   q=2.65, slit len 0.002, slit r 0.55

net area 250.00 cm². How to cut: tape this sheet UNDER the clear plastic (or on top for opaque sheet).
1. Cut along the centre of the black outline. 2. Knife-cut the red slits exactly between the end ticks (no material removed).
3. Punch the 6 blue crosshairs (line points), keep >= 3 mm from the edge. 4. Write the code on the canopy.

50 mm: measure this after printing

100 mm: measure this after printing

Print at 100% / Actual size (NOT 'fit to page').




B5 (best)   q=2.80, slit len 0.074, slit r 0.28

net area 250.00 cm². How to cut: tape this sheet UNDER the clear plastic (or on top for opaque sheet).
1. Cut along the centre of the black outline. 2. Knife-cut the red slits exactly between the end ticks (no material removed).
3. Punch the 6 blue crosshairs (line points), keep >= 3 mm from the edge. 4. Write the code on the canopy.

50 mm: measure this after printing

100 mm: measure this after printing

Print at 100% / Actual size (NOT 'fit to page').




B6 (best)   q=2.29, slit len 0.009, slit r 0.41

net area 250.00 cm². How to cut: tape this sheet UNDER the clear plastic (or on top for opaque sheet).
1. Cut along the centre of the black outline. 2. Knife-cut the red slits exactly between the end ticks (no material removed).
3. Punch the 6 blue crosshairs (line points), keep >= 3 mm from the edge. 4. Write the code on the canopy.

50 mm: measure this after printing

100 mm: measure this after printing

Print at 100% / Actual size (NOT 'fit to page').




M1 (middle)   q=4.26, slit len 0.207, slit r 0.30

net area 250.00 cm². How to cut: tape this sheet UNDER the clear plastic (or on top for opaque sheet).
1. Cut along the centre of the black outline. 2. Knife-cut the red slits exactly between the end ticks (no material removed).
3. Punch the 6 blue crosshairs (line points), keep >= 3 mm from the edge. 4. Write the code on the canopy.

50 mm: measure this after printing

100 mm: measure this after printing

Print at 100% / Actual size (NOT 'fit to page').




M2 (middle)   q=5.83, slit len 0.001, slit r 0.65

net area 250.00 cm². How to cut: tape this sheet UNDER the clear plastic (or on top for opaque sheet).
1. Cut along the centre of the black outline. 2. Knife-cut the red slits exactly between the end ticks (no material removed).
3. Punch the 6 blue crosshairs (line points), keep >= 3 mm from the edge. 4. Write the code on the canopy.

50 mm: measure this after printing

100 mm: measure this after printing

Print at 100% / Actual size (NOT 'fit to page').




M3 (middle)   q=4.19, slit len 0.240, slit r 0.65

net area 250.00 cm². How to cut: tape this sheet UNDER the clear plastic (or on top for opaque sheet).
1. Cut along the centre of the black outline. 2. Knife-cut the red slits exactly between the end ticks (no material removed).
3. Punch the 6 blue crosshairs (line points), keep >= 3 mm from the edge. 4. Write the code on the canopy.

50 mm: measure this after printing

100 mm: measure this after printing

Print at 100% / Actual size (NOT 'fit to page').




M4 (middle)   q=5.81, slit len 0.002, slit r 0.27

net area 250.00 cm². How to cut: tape this sheet UNDER the clear plastic (or on top for opaque sheet).
1. Cut along the centre of the black outline. 2. Knife-cut the red slits exactly between the end ticks (no material removed).
3. Punch the 6 blue crosshairs (line points), keep >= 3 mm from the edge. 4. Write the code on the canopy.

50 mm: measure this after printing

100 mm: measure this after printing

Print at 100% / Actual size (NOT 'fit to page').




M5 (middle)   q=5.02, slit len 0.115, slit r 0.50

net area 250.00 cm². How to cut: tape this sheet UNDER the clear plastic (or on top for opaque sheet).
1. Cut along the centre of the black outline. 2. Knife-cut the red slits exactly between the end ticks (no material removed).
3. Punch the 6 blue crosshairs (line points), keep >= 3 mm from the edge. 4. Write the code on the canopy.

50 mm: measure this after printing

100 mm: measure this after printing

Print at 100% / Actual size (NOT 'fit to page').




M6 (middle)   q=4.19, slit len 0.244, slit r 0.47

net area 250.00 cm². How to cut: tape this sheet UNDER the clear plastic (or on top for opaque sheet).
1. Cut along the centre of the black outline. 2. Knife-cut the red slits exactly between the end ticks (no material removed).
3. Punch the 6 blue crosshairs (line points), keep >= 3 mm from the edge. 4. Write the code on the canopy.

50 mm: measure this after printing

100 mm: measure this after printing

Print at 100% / Actual size (NOT 'fit to page').




W1 (worst)   q=7.89, slit len 0.248, slit r 0.56

net area 250.00 cm². How to cut: tape this sheet UNDER the clear plastic (or on top for opaque sheet).
1. Cut along the centre of the black outline. 2. Knife-cut the red slits exactly between the end ticks (no material removed).
3. Punch the 6 blue crosshairs (line points), keep >= 3 mm from the edge. 4. Write the code on the canopy.

50 mm: measure this after printing

100 mm: measure this after printing

Print at 100% / Actual size (NOT 'fit to page').




W2 (worst)   q=8.00, slit len 0.157, slit r 0.28

net area 250.00 cm². How to cut: tape this sheet UNDER the clear plastic (or on top for opaque sheet).
1. Cut along the centre of the black outline. 2. Knife-cut the red slits exactly between the end ticks (no material removed).
3. Punch the 6 blue crosshairs (line points), keep >= 3 mm from the edge. 4. Write the code on the canopy.

50 mm: measure this after printing

100 mm: measure this after printing

Print at 100% / Actual size (NOT 'fit to page').




W3 (worst)   q=6.84, slit len 0.250, slit r 0.37

net area 250.00 cm². How to cut: tape this sheet UNDER the clear plastic (or on top for opaque sheet).
1. Cut along the centre of the black outline. 2. Knife-cut the red slits exactly between the end ticks (no material removed).
3. Punch the 6 blue crosshairs (line points), keep >= 3 mm from the edge. 4. Write the code on the canopy.

50 mm: measure this after printing

100 mm: measure this after printing

Print at 100% / Actual size (NOT 'fit to page').




W4 (worst)   q=7.99, slit len 0.146, slit r 0.46

net area 250.00 cm². How to cut: tape this sheet UNDER the clear plastic (or on top for opaque sheet).
1. Cut along the centre of the black outline. 2. Knife-cut the red slits exactly between the end ticks (no material removed).
3. Punch the 6 blue crosshairs (line points), keep >= 3 mm from the edge. 4. Write the code on the canopy.

50 mm: measure this after printing

100 mm: measure this after printing

Print at 100% / Actual size (NOT 'fit to page').




W5 (worst)   q=7.86, slit len 0.163, slit r 0.63

net area 250.00 cm². How to cut: tape this sheet UNDER the clear plastic (or on top for opaque sheet).
1. Cut along the centre of the black outline. 2. Knife-cut the red slits exactly between the end ticks (no material removed).
3. Punch the 6 blue crosshairs (line points), keep >= 3 mm from the edge. 4. Write the code on the canopy.

50 mm: measure this after printing

100 mm: measure this after printing

Print at 100% / Actual size (NOT 'fit to page').



W6 (worst)   q=7.96, slit len 0.240, slit r 0.27

net area 250.00 cm². How to cut: tape this sheet UNDER the clear plastic (or on top for opaque sheet).
1. Cut along the centre of the black outline. 2. Knife-cut the red slits exactly between the end ticks (no material removed).
3. Punch the 6 blue crosshairs (line points), keep >= 3 mm from the edge. 4. Write the code on the canopy.

50 mm: measure this after printing

100 mm: measure this after printing

Print at 100% / Actual size (NOT 'fit to page').